

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

Architectural Panel End Section...






Fig. 2


Architectural Panel End Return Section...

Fig. 3

Architectural Panel Bottom Section...



Architectural Panel Bottom Section...



Wall Panel Section...






Fig. 8

Fig. 8

Architectural Panel @ 4-Sided Mid Rib




Architectural Panel @ Bearing Pocket Seat



Architectural Panel


@ Thermally Broken Closed-End Rib Joint




Architectural Panel

@ Rib


Fig. 12



@Floor-to-Floor Fire Barrier




Hardwall Panel @ Mid Rib




[illegible]

—


Hardwall Panel @ Horizontal Joint



Wall Panel



Load-Bearing Wall Panel



Wall Panel





Fig. 20

Multi-unit Residential Wall Panel @ Middle Rib



Multi-unit Residential Panel @ End Rib




FIG. 22

Multi-unit Residential Panel @ Corner Ribs





FIG. 23

Multi-unit Residential Panel

@ Top Rib



Multi-unit Residential Panel @ Bottom Rib

